

# VERNON PUBLIC UTILITIES

## INSPECTIONS OF ELECTRIC UTILITY SUBSTATIONS

Substation inspection procedures ensure a minimum of two comprehensive inspections annually. These comprehensive inspections may encompass various tasks, including battery inspections, infrared inspections, and general station evaluations.

Note that record keeping policies implemented after 2018 quantify inspections by the number of individual inspections conducted, rather than the number of substations visited. Regardless of the reporting method, all substations undergo daily visual inspections to ensure their continued safe and reliable operation.

YEAR OF INSPECTION	DUE	OUTSTANDING	UNITS
2022 - 2023	134	0	Inspections
2021 - 2022	82	0	Inspection
2020- 2021	110	0	Inspection
2019 - 2020	124	0	Inspections

# VERNON PUBLIC UTILITIES

## INSPECTIONS OF ELECTRIC UTILITY SUBSTATIONS

YEAR OF INSPECTION	DUE	OUTSTANDING	UNITS
2018 - 2019	77	0	Inspections
2017 - 2018	36	0	Substations
2016 - 2017	36	0	Substations
2015 - 2016	9	0	Substations
2014 - 2015	16	0	Substations
2013 - 2014	16	0	Substations